

Photo 1 – Main Wreckage



Photo 2 – Damage to the Starter Ring and Starter Teeth



Photo 3 – Tree Strike



Photo 4 – Sheave Impact Mark



Photo 5 – Sheave Impact Mark



Photo 6 – Drained Fuel From Helicopter (Robinson Photo)



Photo 7 – Blade A (Robinson Photo)



Photo 8 – Blade B (Robinson Photo)