



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety

Western Pacific Region

May 9, 2020

ACCIDENT REPORT PHOTOGRAPHS

WPR20CA151

This document contains 03 embedded photos.

(4 pages)



Photo 1: Damage to empennage (FAA)



Photo 2: Damage to empennage (FAA)



Photo 3: Damage to fuselage and landing gear (FAA)