



**Photo 1 – View of the left side propeller after the airplane landed (courtesy of the pilot).**





**Photo 2 – View of the fractured left side propeller blade after the airplane landed (courtesy of the pilot).**



**Photo 3 – View of the fractured left side propeller blade after the airplane landed (courtesy of the pilot).**