



Photo 1 – Burnt Batteries and Pen, Photo provided by Air Evac LifeTeam



Photo 2 – Burnt Battery, Photo provided by Air Evac LifeTeam



Photo 3 – Helicopter Restraints, Photo provided by Air Evac LifeTeam



Photo 4 – Helicopter Restraints in Detail, Photo provided by Air Evac LifeTeam



Photo 5 – Paramedic’s Flight Suit, Photo provided by Air Evac LifeTeam




Photo 6 – Flight Suit Burn Damage in Detail, Photo provided by Air Evac LifeTeam



Photo 7 – Flight Jacket, Photo provided by Air Evac LifeTeam



Photo 8 – Flight Jacket, Detail, Photo provided by Air Evac LifeTeam