



Photo 1 – Airplane Damage (FAA Photo)



Photo 2 – Closeup of Left Wing (FAA Photo)



Photo 3 – Engine (NTSB Photo)