



**Photo 1 – Right Wing Aileron Damage (Photo courtesy of flight instructor)**



**Photo 2 – Stabilator damage from rear (Photo courtesy of aircraft owner)**





**Photo 3 - Stabilator damage right side (Photo courtesy of aircraft owner)**