



Photo 1 –N74349, at the accident site.



Photo 2 -Right rear view.



Photo 3 – Path from the end of the runway to the accident site.



Photo 4 – Engine. Photo courtesy of Lycoming Engines.



Photo 5 -Aileron carry-through cable