



Photo 1 – N7677C, front view. Photo courtesy of the FAA.



Photo 2 – N7677C, right wing. Photo courtesy of the FAA.



Photo 3 – N7677C, Top view. Photo courtesy of the FAA.



Photo 4 – Right wing. Photo courtesy of the FAA.



Photo 5 – Right wing and empennage. Photo courtesy of the FAA.



Photo 6 – Overhead view showing the two fire damaged houses and detached garage, along with the right wing. Photo courtesy of the West Jordan Police Department.



Photo 7 – Photo showing the left main landing gear and ash from the left wing. Photo courtesy of the FAA.



Photo 8 – Image showing the GPS flight path. The blue arrows point to the direction of travel. Image NTSB