



Photo 1 – Right-side view of N3388T, showing substantial damage to the fuselage. Photo courtesy of the pilot.



Photo 2 – Left-side view of N3388T, showing substantial damage to the fuselage. Photo courtesy of the pilot.