



Photo 1 –N101YY, showing damage to the right wing. Photo courtesy of the pilot.




Photo 2 – Total fuel drained from both tanks. Photo NTSB