

Phot



Photo 1: Damage to the Upper Surface of the Left Wing Damage



Photo 2: Damage to the Lower Surface of the Left Wing



Photo 3: Damage to the Windshield