



Photo 1 – Front view of the airplane where it came to rest. (Photo courtesy of the FAA)



Photo 2 – View of collapsed nose landing gear. (Photo courtesy of FAA)



Photo 3 – View of the damage to the fuselage and empennage. (Photo courtesy of FAA)