



Photo 1 – Engine Keel Beam Damage (Courtesy of FAA)



Photo 2 - Engine Keel Beam Damage (Courtesy of FAA)



Photo 3 – Instrument Panel (Courtesy of Pilot)



Photo 4 – Landing Gear Switch (Courtesy of Pilot)



Photo 5 - Flap Switch (Courtesy of Pilot)