



Photo 1 – Damage to fuselage (photo courtesy of operator)



Photo 2 - Damage to fuselage (photo courtesy of operator)