



**Photo 1 – Front View of Airplane, Photo Courtesy of FAA**





**Photo 2 – Left Wing Damage, Photo Courtesy of FAA**





**Photo 3 – Right Wing Damage, Photo Courtesy of FAA**