



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Eastern Region

Photo Array

ERA22LA113



Photo 1 – View of airplane where it came to rest, inverted in the snow next to the runway. (Photo courtesy of the FAA)



Photo 2 – View of the left side of the airplane. (Photo courtesy of the FAA)



Photo 3 – View of the airplane from the tail looking forward. (Photo courtesy of the FAA)



Photo 4 – View of the right side of the airplane. (Photo courtesy of the FAA)