



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Eastern Region

Photo Array

ERA22LA158



Photo 1 – Rear view of airplane inverted next to the runway. (Photo courtesy of the FAA)



Photo 2 – View of the right side of the airplane. (Photo courtesy of the FAA)



Photo 3 – View of the damage to the fuselage. (Photo courtesy of the FAA)