



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Eastern Region

Photo Array

ERA22LA210



Photo 1 – Rear view of airplane and left wing tip. (Photo courtesy of the FAA)



Photo 2 – View of the left wing tip and bent elevator. (Photo courtesy of the FAA)