



**NATIONAL TRANSPORTATION SAFETY BOARD**

Office of Aviation Safety  
Eastern Region

**Photo Array**

**ERA21LA196**



**Photo 1 – Front view of glider where it came to rest against a parked airplane. (Photo courtesy of the FAA)**



**Photo 2 – View of the right side of the glider. (Photo courtesy of the FAA)**



**Photo 3 – View of the cockpit. (Photo courtesy of the FAA)**