

CEN24LA047

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Front of airplane (Courtesy of FAA)



Photograph 2 - Right side of airplane (Courtesy of FAA)



Photograph 3 - Damage to left float (Courtesy of FAA)