

ERA24LA131

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Front View of Airplane and Pothole (Courtesy of FAA)



**Photograph 2 - View of LH Side of Airplane and Damage to MLG and Propeller
(Courtesy of FAA)**



Photograph 3 - Damage of Lower Fuselage (Courtesy of FAA)



Photograph 4 - Damage to LH Wing Root (Courtesy of FAA)