

Proassist III photos following
Recovery



Photo included in 11/10/2021 email from owner to Sector San Juan.

Proassist III, shoreside in Yabucoa, Puerto Rico, being held out of the water by means of chains held by four pullers..

Owner said after portion of superstructure separated from vessel after sinking and before recovery.



Proassist III photo from 11/17/2021
USCG Sector San Juan examination
of the vessel.

Deck house/superstructure section
missing from the main deck.
Section came away from vessel
after sinking and before recovery.



Proassist III photo from 11/17/2021 USCG Sector San Juan examination of the vessel.

Photo of the main deck of the *Proassist III* taken from the aft port corner of the vessel.



Proassist III photo from 11/17/2021
USCG Sector San Juan examination of the vessel.

Photo of non-watertight bulkhead (Deep frame) below main deck in the flanking rudder compartment.