

PROP MODEL  
PHC-JSYF-1RF  
PROP S/N FP1240B  
REG NO N304MA  
WORK ORDER  
2702-02-2018

Don Maxwell Aviation Services, Inc.

Longview, Tx 75602  
Phone [REDACTED]

DATE 3/2/2018  
A/C TSN 2814  
PROP TT 17234  
TSPOH 17234  
HOBBS 2814

### Prop Entries

(4) Check prop for nicks and abrasion. Remove spinner, check for cracks. Check hub & blades for leakage & security. Reinstall spinner.

I certify this prop has been inspected in accordance with a 100 hr inspection and found in an airworthy condition. Don Maxwell A&P [REDACTED]

DATE: 3/2/2018

SIGNED: [REDACTED]

Work Order: 2702-02-2018

Printed by EBis 3 (datcomedia.com)

PROP MODEL  
PHC-JSYF-1RF  
PROP S/N FP1240B  
REG NO N304MA  
WORK ORDER  
2934-03-2019

Don Maxwell Aviation Services, Inc.

Longview, Tx 75603  
Phone [REDACTED]

DATE 7/8/2019  
A/C TSN 2454 42  
PROP TT 1863 82  
TSPOH 1863 82  
HOBBS 2454 42

### Prop Entries

(4) Removed prop for engine overhaul. Check prop for nicks and abrasion. Remove spinner, check for cracks. Check hub & blades for leakage & security. Reinstall prop & spinner.

I certify this prop has been inspected in accordance with a 100 hr inspection and found in an airworthy condition. Don Maxwell A&P [REDACTED]

DATE: 7/8/2019

SIGNED: [REDACTED]

Work Order: 2934-03-2019

Printed by EBis 3 (datcomedia.com)

RECORDS

ANTI-ICE AND DE-ICE

MAINTENANCE

INSPECTION AND

Date	Propeller	A/C	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
------	-----------	-----	--

TSN TSO  
 PROP MODEL:  
 PHC-J3YF-1RF  
 PROP S/N: FP1240B  
 REG. NO: N304MA  
 WORK ORDER:  
 3246-07-2020

**Don Maxwell Aviation Services, Inc.**

██████████  
 Longview, Tx 75603  
 Phone ██████████

DATE: 8/25/2020  
 A/C TSN: 2559.4  
 PROP TT: 1968.8  
 TSPOH: 1968.8  
 HOBBS: 2559.4

**Prop Entries**

(4) Check prop for nicks and abrasion. Remove spinner, check for cracks. Check hub & blades for leakage & security. Reinstall spinner.... (14) Removed prop for IRAN. Reinstalled prop after repairs by Byam Propeller.

I certify this prop has been inspected in accordance with a 100 hr inspection and found in an airworthy condition. Adam Clark A&P ██████████

DATE: 8/25/2020

SIGNED: ██████████

Work Order: 3246-07-2020

Printed by EBis 3 (datcomedia.com)

PROP MODEL:  
 PHC-J3YF-1RF  
 PROP S/N: FP1240B  
 REG. NO: N304MA  
 WORK ORDER:  
 3515-08-2021

**Don Maxwell Aviation Services, Inc.**

██████████  
 Longview, Tx 75603  
 Phone ██████████

DATE: 9/18/2021  
 A/C TSN: 2641.3  
 PROP TT: 2050.7  
 TSPOH: 2050.7  
 HOBBS: 2641.3

**Prop Entries**

(4) Check prop for nicks and abrasion. Remove spinner, check for cracks. Check hub & blades for leakage & security. Reinstall spinner.

I certify this prop has been inspected in accordance with a 100 hr inspection and found in an airworthy condition. Don Maxwell A&P ██████████

DATE: 9/18/2021

SIGNED: ██████████

Work Order: 3515-08-2021

Printed by EBis 3 (datcomedia.com)



