



Stephen Stein
Senior Aviation Accident Investigator
Aviation Safety - Western Pacific Region

Date: May 12, 2023
Subject: WPR22FA196 - Oroville, California
Contact: Dannie McClendon, Eyewitness

Mr. McClendon stated that when they flew 2 weeks prior to the accident he was trying to determine which position the selector needed to be in and the accident pilot swatted his hand away and put the large end of the handle over the L tank position.