

Master, Riverside


Statement of Fact

Subject- Port state control Report of Inspection Form B

This is reference to Deficiency no.1 with code 13101, found during USCG Safety Inspection, which was dated 21 March 2021 and records Deficiency as below-

Precautions shall be taken to prevent any oil that may escape under pressure from any pump, filter or heater coming into contact with heated surfaces. Main diesel engine was found to have fuel leaking from No.1 and 5 fuel Oil Pumps. Excess amount of fuel oil was collecting on top of the main diesel engine.


Corrective Action- No.1 and 5 Fuel Pump Leakage arrested photos as below for corrective actions taken. All fuel Pumps checked for oil leakage, No leakage observed.



No.1,2 and 3 Fuel Pumps



No.1 Fuel Pump



No.4, 5 and 6 Fuel Pumps

Master

Capt. Yashpal Singh Chahal

VESSEL NAME : Riverside
PORT OF REG: Valletta
REG: Malta
NO.: 9412464
CALL SIGN: 9HA5289
IMO: 62856
NET: 35798
POWER (BHP): 19380

Chief Engineer

Lloyd D Almeida