File No.: 19-0635

# PHOTO SHEET NO. 1

VESSEL : F/V SASHA LEE

**Condition and Value Survey** 

DATE OF SURVEY : August 7, 2019 LOCATION : New Bedford, MA TAKEN BY : Mark A. Bisnette



DESCRIPTION: Starboard bow view of vessel moored in New Bedford, MA.

File No.: 19-0635


# PHOTO SHEET NO. 2

VESSEL : F/V SASHA LEE

**Condition and Value Survey** 

DATE OF SURVEY : April 8, 2016

LOCATION : New Bedford, MA TAKEN BY : Mark A. Bisnette



DESCRIPTION: Stern view of vessel (2016)

File No.: 19-0635

# PHOTO SHEET NO. 3

VESSEL : F/V SASHA LEE

**Condition and Value Survey** 

DATE OF SURVEY : August 7, 2019 LOCATION : New Bedford, MA TAKEN BY : Mark A. Bisnette



DESCRIPTION: View of cargo work deck looking forward.

File No.: 19-0635

# PHOTO SHEET NO. 4

VESSEL : F/V SASHA LEE

**Condition and Value Survey** 

DATE OF SURVEY : August 7, 2019 LOCATION : New Bedford, MA TAKEN BY : Mark A. Bisnette



DESCRIPTION: View of work deck looking aft.


File No.: 19-0635

# PHOTO SHEET NO. 5

VESSEL : F/V SASHA LEE

**Condition and Value Survey** 

DATE OF SURVEY : August 7, 2019 LOCATION : New Bedford, MA TAKEN BY : Mark A. Bisnette



DESCRIPTION: View of pilothouse navigation station.

File No.: 19-0635

# PHOTO SHEET NO. 6

VESSEL : F/V SASHA LEE

**Condition and Value Survey** 

DATE OF SURVEY : August 7, 2019 LOCATION : New Bedford, MA TAKEN BY : Mark A. Bisnette



DESCRIPTION: View of galley

File No.: 19-0635

#### PHOTO SHEET NO. 7

VESSEL : F/V SASHA LEE

**Condition and Value Survey** 

DATE OF SURVEY : August 7, 2019 LOCATION : New Bedford, MA TAKEN BY : Mark A. Bisnette



DESCRIPTION: View of main diesel engine

File No.: 19-0635

# PHOTO SHEET NO. 8

VESSEL : F/V SASHA LEE

**Condition and Value Survey** 

DATE OF SURVEY : August 7, 2019 LOCATION : New Bedford, MA TAKEN BY : Mark A. Bisnette



DESCRIPTION: View of Caterpillar genset

File No.: 19-0635

# PHOTO SHEET NO. 9

VESSEL : F/V SASHA LEE

**Condition and Value Survey** 

DATE OF SURVEY : August 7, 2019 LOCATION : New Bedford, MA TAKEN BY : Mark A. Bisnette



DESCRIPTION: View of bilge pumping system

File No.: 19-0635

# PHOTO SHEET NO. 10

VESSEL : F/V SASHA LEE

**Condition and Value Survey** 

DATE OF SURVEY : August 7, 2019 LOCATION : New Bedford, MA TAKEN BY : Mark A. Bisnette



DESCRIPTION: View of Caterpillar cargo pump engine

File No.: 19-0635

#### PHOTO SHEET NO. 11

VESSEL : F/V SASHA LEE

**Condition and Value Survey** 

DATE OF SURVEY : August 7, 2019 LOCATION : New Bedford, MA TAKEN BY : Mark A. Bisnette



DESCRIPTION: View of cargo hold

File No.: 19-0635

#### PHOTO SHEET NO. 12

VESSEL : F/V SASHA LEE

**Condition and Value Survey** 

DATE OF SURVEY : August 7, 2019 LOCATION : New Bedford, MA TAKEN BY : Mark A. Bisnette



DESCRIPTION: View of steering gear in lazarette

File No.: 19-0635

#### PHOTO SHEET NO. 13

VESSEL : F/V SASHA LEE

**Bottom Survey & Audio Gauge Survey** 

DATE OF SURVEY : August 1, 2019 LOCATION : Fairhaven, MA. TAKEN BY : Jay C. Sousa



DESCRIPTION: Starboard bow view of the vessel while short hauled at Fairhaven Shipyard.


File No.: 19-0635

# PHOTO SHEET NO. 14

VESSEL : F/V SASHA LEE

**Bottom Survey & Audio Gauge Survey** 

DATE OF SURVEY : August 1, 2019 LOCATION : Fairhaven, MA. TAKEN BY : Jay C. Sousa



DESCRIPTION: View of the vessels stern.

File No.: 19-0635

#### PHOTO SHEET NO. 15

VESSEL : F/V SASHA LEE

**Bottom Survey & Audio Gauge Survey** 

DATE OF SURVEY : August 1, 2019 LOCATION : Fairhaven, MA. TAKEN BY : Jay C. Sousa



DESCRIPTION: View of the vessels propeller, kort nozzle and rudder.

File No.: 19-0635

# PHOTO SHEET NO. 16

VESSEL : F/V SASHA LEE

**Bottom Survey & Audio Gauge Survey** 

DATE OF SURVEY : August 1, 2019 LOCATION : Fairhaven, MA. TAKEN BY : Jay C. Sousa



DESCRIPTION: View of the vessels bottom starboard side.