



**Survival Factors Investigation Attachment  
Seating Chart Addendum**

**Pala Mesa, California**

**HWY20FH003**

(2 pages)

### Seating Chart Addendum

The table below lists those occupants of the crash bus whose location could not be verified

Passenger Sex	Age	Injury Severity	Remarks
F	62	Serious	Believed to have been seated 3 <sup>rd</sup> row left on aisle. Not confirmed
F	59	Serious	Front of bus, right side window. No further info
F	73	Fatal	Ejected, found underneath bus
F	67	Fatal	Found by FD wedged between two seats near the front of bus, on the right side.
M	25	Serious	Towards rear of bus
M	61	Minor	Reported near middle of bus, right side, window Note: Matches description of subject in seat row #6 right side
M	39	Serious	No further info available