



**Survival Factors Attachment-
Survival Factors
Photographs**

Pala Mesa, California

HWY20FH003

(4 pages)



Photo #1 Overhead view of the overturned bus over the embankment (Source: CHP)



Photo #2 Close-up of the overturned bus over the embankment (Source: CHP)



Photo #3 On-scene traffic control performed by CHP (Source CHP)



Photo #4 Overhead view of traffic control performed by Caltrans (Source: CHP)



Photo #5 Tow trucks pulling bus up from the embankment (Source: CHP)