

Elmwood Shop Manager's Turnover 7/27/2023 5:30 a.m.

Rail	Trolley		VRC/RVARD
		Be Careful backing out of the shop. Switches must be open in the direction of movement	
			Sweeps
		Switch 66 (24 & 25 Rail) - MANUAL OPERATION - Vetag will not work	
2 Rail			Sliders
3 Rail	9018	Pre A Inspection	
	9087	Pre B Inspection	Housecleans
4 Rail	9020	A inspection	
	9074	A inspection	
	9065	A inspection	
5 Rail	9072	Clearance Bar Repair - Phillips	Claims/Camera Cars
	9075	Brake Project Working - Rotors Installed(Needs to be Torqued) New hardware in storeroom	
			9003 24/2 HOLD SIGN
6 Rail	9054	10-Day Ali	
	9028	10-Day Pointer	
	9083	10-Day Holloway	
14 Rail			
	9063	Propulsion	
	9091	Brake Issue WND	
15 Rail	H/Cleans	Good Cars	Fare Box ext #4020 (215) 964-4721
16 Rail	10 Days	Good Cars	Revenue notified 7/27/23
17 Rail	10 Days	Good Cars	9002 - Full Fare Box 9055- Full Fare Box
18 Rail	9062	DC/DC converter Hood	9050 9026
Note :			
	9077	Collision Avoidance - Please Hold	25 Rail Deferred Repairs Radio #4083
			9107 CBTC NPR Needed Compressor Problem 2328 ADMT not working
			9108 CBTC testing Needed HVAC - Hot Car
			9045 CBTC NPR Needed
			9101 CBTC Doppler A1b Unit Air Leak
			9111 CBTC NPR Needed
			9048 Propulsion Trans. Dispatcher #6229
			9097 Propulsion Repeater - GPA Trouble Cars for Decorations
			9046 9055 9034 9090 9104 9095 9053 9080
			Fern Rock Units
13-1	9033	Rain Water Roof Leaking	2 Park Air Portions (0) Chop Blwr Mtrs
13-2	9006	Heavy Vibration from Chopper Blower	4 Non Park Air Potions
			4 Frames (0) Good Used Frames
			2 Compressor
7-1			9-1 9037 Rear Truck Grnd Field- Woodland
7/2	2194	Work Car	9-2 9082 Front Truck Grnd Field- Woodland
7-3	9070	Accident - ON HOLD	9-3 9051 Front Track Brake- Woodland (See Notes)
7-4	9085	*NOT FOR SERVICE*	9-4
7-5	9025	*NOT FOR SERVICE*	
			10-1 Pre Inspection
8-1	9052	Needs HVAC GTT(Gas Temp Thermo) 7/28/23 AM	10-2 Pre Inspection
8-2	9089	Trainline needs further attention/post Rates	10-3 Pre Inspection
8-3	9106	Needs NPR	
8-4			
8-5			11-1 2326 Inspection Training Car
			11-2 9077 Collision avoidance
			11-3 9068 TESTING WI FI
			12-1 9109 Motor control box repair - Woodland

Elmwood Shop Manager's Turnover 7/27/2023 7:15 a.m.

Rail	Trolley		VRC/RVARD
		Be Careful backing out of the shop. Switches must be open in the direction of movement	
			Sweeps
		Switch 66 (24 & 25 Rail) - MANUAL OPERATION - Vetag will not work	
2 Rail			Sliders
3 Rail	9018	Pre A Inspection	
	9087	Pre B Inspection	Housecleans
4 Rail	9020	A inspection	
	9074	A inspection	
	9065	A inspection	
5 Rail	9072	Clearance Bar Repair - Phillips	Claims/Camera Cars
	9075	Brake Project Working - Rotors Installed(Needs to be Torqued) New hardware in storeroom	
	9107	d5 Compressor CBTC	9003 24/2 HOLD SIGN
6 Rail			
14 Rail			
	9063	Propulsion	
	9091	Brake Issue WND	
15 Rail	H/Cleans	Good Cars	Fare Box ext #4020 (215) 964-4721
16 Rail	10 Days	Good Cars	Revenue notified 7/27/23
17 Rail	10 Days	Good Cars	9002 - Full Fare Box 9055- Full Fare Box
18 Rail	9062	DC/DC converter Hood	9050 9026

Note :	9077	Collision Avoidance - Please Hold	25 Rail	Deferred Repairs	Radio #4083
			9107	CBTC NPR Needed Compressor Problem	2328 ADMT not working
			9108	CBTC testing Needed HVAC - Hot Car	
			9045	CBTC NPR Needed	
			9101	CBTC Doppler A1b Unit Air Leak	
			9111	CBTC NPR Needed	
			9048	Propulsion	Trans. Dispatcher #6229
			9097	Propulsion Repeater - GPA Trouble	Cars for Decorations
					9046 9055 9034 9090
					9104 9095 9053 9080

Fern Rock Units					
13-1	9033	Rain Water Roof Leaking	2	Park Air Portions (0) Chop Blwr Mtrs	
13-2	9006	Heavy Vibration from Chopper Blower	4	Non Park Air Portions	
			4	Frames (0) Good Used Frames	
			2	Compressor	
7-1			9-1	9037	Rear Truck Grnd Field- Woodland
7/2	2194	Work Car	9-2	9082	Front Truck Grnd Field- Woodland
7-3	9070	Accident - ON HOLD	9-3	9051	Front Track Brake- Woodland (See Notes)
7-4	9085	*NOT FOR SERVICE*	9-4		
7-5	9025	*NOT FOR SERVICE*			
			10-1		Pre Inspection
8-1	9052	Needs HVAC GTT(Gas Temp Thermo) 7/28/23 AM	10-2		Pre Inspection
8-2	9089	Trainline needs further attention/post Rates	10-3		Pre Inspection
8-3	9106	Needs NPR			
8-4					
8-5			11-1	2326	Inspection Training Car
			11-2	9077	Collision avoidance
			11-3	9068	TESTING WI FI
			12-1	9109	Motor control box repair - Woodland

Elmwood Shop Manager's Turnover 7/27/2023 1:40 p.m.

Rail	Trolley			VRC/RVARD
		Be Careful backing out of the shop. Switches must be open in the direction of movement		
				Sweeps
		Switch 66 (24 & 25 Rail) - MANUAL OPERATION - Vetag will not work		
2 Rail				Sliders
3 Rail	9018	Pre A Inspection		
	9087	Pre B Inspection		Housecleans
	9018	Pre A Inspection		
4 Rail	9020	Insp repairs , post rates (D.Saunders has repairs)		
	9074	Insp repairs , post rates ((M.Thornton BE Inspection)		
	9065	Insp repairs , post rates ((M.Thornton BE Inspection)		
5 Rail				Claims/Camera Cars
	9075	Brake Project Working - Rotors Installed(Needs to be Torqued) New hardware in storeroom		
	9107	D5 Compressor - WND (Needs wiring & leak test CBTC (Cradle missing)		
6 Rail	2326	PCC PM Training		
	9063	Propulsion - Mohammed		
14 Rail	9091	Brake Issue WND		
	9038	Air Pressure problem		
15 Rail	H/Cleans			Fare Box ext #4020 (215) 964-4721
16 Rail	10 Days			
17 Rail	10 Days			
18 Rail				
Note :			25 Rail	Deferred Repairs
	9077	Collision Avoidance - Please put on hold rail		
	9068	Dead recogning testing in service	9045	CBTC NPR Needed
			9101	CBTC Doppler A1b Unit Air Leak
	9108	HVAC needs repair before CBTC testing	9111	CBTC NPR Needed
			9048	Propulsion
			9097	Propulsion Repeater - GPA Trouble
				Trans. Dispatcher #6229 Cars for Decorations 9046 9055 9034 9090 9104 9095 9053 9080
			Fern Rock Units	
13-1			2	Park Air Portions (0) Chop Blwr Mtrs
13-2			4	Non Park Air Potions
			4	Frames (0) Good Used Frames
			2	Compressor
7-1			9-1	9037 Rear Truck Grnd Field- Woodland
7/2	2194	Work Car	9-2	9082 Front Truck Grnd Field- Woodland
7-3	9070	Accident - ON HOLD	9-3	9051 Front Track Brake- Woodland (See Notes)
7-4	9085	*NOT FOR SERVICE*	9-4	
7-5	9025	*NOT FOR SERVICE*		
			10-1	9105 Pre Inspection
8-1	9052	Needs HVAC GTT(Gas Temp Thermo) 7/28/23 AM	10-2	Pre Inspection
8-2	9089	Trainline needs further attention/post Rates	10-3	Pre Inspection
8-3	9106	Needs NPR		
8-4	9108	CBTC testing Needed HVAC - Hot Car		
8-5			11-1	Collision Avoidance testing (9077 in service)
			11-2	Dead reckoning testing (9068 in service - 10 day @)
			11-3	
			12-1	9109 Motor control box repair - Woodland

Elmwood Shop Manager's Turnover 7/27/2023 10:00 p.m.

Be Careful backing out of the shop. Switches must be open in the direction of movement			D.Hood
Switch 66 (24 & 25 Rail) - MANUAL OPERATION - Vetag will not work			Sweeps D.McCollin
2 Rail			Sliders
3 Rail	9018	Pre A Inspection	
	9087	Pre B Inspection	Housecleans
	9018	Pre A Inspection	
4 Rail			
	9074	Post Rates	
	9065	Post Rates	
5 Rail			Claims/Camera Cars
	9075	Brake Project Working - Rotors Installed(Needs to be Torqued) New hardware in storeroom	
	9107	CBTC (Cradle missing)	
6 Rail	9034	10 Day- G.Stowers	
14 Rail	9038	Compressor not running	
	9084	Cover Sheet 10 Day	
15 Rail	H/Cleans	9009 9102 9091 9092 9042 9002 9005	Fare Box ext #4020 (215) 964-4721
16 Rail	10 Days	9076 9060	
17 Rail	10 Days	9034 9043 9078	
18 Rail	9062	DC/DC Converter (Repeater)	
Note :			25 Rail
	9077	Collision Avoidance - Please put on hold rail	Deferred Repairs
			Radio #4083
	9108	HVAC needs repair before CBTC testing	9045 CBTC NPR Needed 2328 ADMT not working
			9101 CBTC Doppler A1b Unit Air Leak
			9111 CBTC NPR Needed
			9048 Propulsion
			9097 Propulsion Repeater - GPA Trouble
			Trans. Dispatcher #6229 Cars for Decorations
			9046 9055 9034 9090
			9104 9095 9053 9080
			Fern Rock Units
13-1	9077	Collision Avoidance	2 Park Air Portions (0) Chop Blwr Mtrs
13-2			4 Non Park Air Potions
			4 Frames (0) Good Used Frames
			2 Compressor
7-1			9-1 9037 Rear Truck Grnd Field- Woodland
7/2	2194	Work Car	9-2 9082 Front Truck Grnd Field- Woodland
7-3	9070	Accident - ON HOLD	9-3 9051 Front Track Brake- Woodland (See Notes)
7-4	9085	*NOT FOR SERVICE*	
7-5	9025	*NOT FOR SERVICE*	
			10-1 9105 Pre Inspection
8-1	9052	Needs HVAC GTT(Gas Temp Thermo)	10-2 Pre Inspection
8-2	9089	Trainline needs further attention/post Rates	10-3 Pre Inspection
8-3	9106	Needs NPR	
8-4	9108	CBTC testing Needed HVAC - Hot Car	
8-5			11-1 2326 Inspection Training Car
			11-2
			11-3
			12-1 9109 Motor control box repair - Woodland
			12-2 9061 Woodland - HVAC Repairs Post Rates