

US Coast Guard photographs

MISLE Case Number: 7624790

Incident Description: Fire on small passenger vessel *Qualifier 105*

Photographer: LT [REDACTED], USCG

Date taken: 03 March 2023

Location: Northern Enterprises Boat Yard, Homer, AK, USA

Environmental Conditions (light, weather, etc.): Clear day

General Comments: No interior illumination inside vessel. All lighting provided by 2 flashlights or built in flash on camera. Camera was a 12 MP iPhone 8 camera.

Images 0242, 0243, 0252, 0253 and 0261.



Image no.: 0242 **Time:** 1002 **Description:** Looking through aft doors into main cabin from fantail.



Image no.: 0243 **Time:** 1002 **Description:** Close up of escape hatch from lower deck into main cabin.



Image no.: 0252 **Time:** 1004 **Description:** Descending port stair in main cabin down to after stateroom compartment.



Image no.: 0254 **Time:** 1005 **Description:** Stateroom J floor area where welding machine was located.



Image no.: 0261 **Time:** 1007 **Description:** Starboard side fuel tank welding area. Photo taken from head doorway looking to starboard.