



## **HIGHWAY ACCIDENT BRIEF PHOTOGRPAHS**

**Upper Marlboro, Maryland**

**HWY16SH016**

(3 pages)



Photograph 1 – The rear of the Cadillac SUV stopped in the northbound lanes of Watkins Park Drive and the pedestrian cross walk – facing north



Photograph 2- The driver's view as he approached Watkins Park Drive – facing east





Photograph 3 – Left front corner of Cadillac SUV showing damage on hood



Photograph 4 – Right front corner of Cadillac SUV