

VEHICLE FACTORS GROUP CHAIRMAN'S FACTUAL REPORT ATTACHMENT

Utah Highway Patrol Post-Crash Level 1 Inspection

Bryce Canyon City, Utah

HWY19MH012

(2 pages)



Report Prepared By:

B. Johnson

<u>Unit #:</u>

Badge #:

U37118

UDOT/Motor Carrier Division 4501 South 2700 West, Box 148240 Salt Lake City, UT 84114-8240 P:(801)965-4892 F:(801)965-4847 Email: UDOTinspections@utah.gov Report Number: UT19IN000282 Inspection Date: 09/20/2019

Start: 11:18 AM MT **End:** 6:02 PM MT

Inspection Level: I - Full HM Inspection Type: None

AMERICA SHENGJIA IN 902 S GREENWOOD A ONTARIO, CA, 91761	VE Li o D a	iver: cense#: te of Birth:	State: CA
USDOT: 2788195 MC/MX#: 929604 State#: Location: ROADSIDE Highway: SR 12 County: GARFIELD	Fax#: Ĺio Da Milepost: Origin: EL		f Lading: NA
VEHICLE IDENTIFICAT Unit Type Make Year St 1 MC FREIG 2017 C	<u>ate Plate Equipment ID</u>	<u>VIN</u> <u>GVWR</u> <u>CVSA#</u> VDT7HDJD9595 26000	Issued# OOS Sticker
Axle # 1 2 Right 1 1/8 1 1/8 Left 1 1/8 1 1/8 Chamber L-20* L-30	2 8		
VIOLATIONS Section Type Unit OOS 392.2-ML F D N	S <u>Citation# VerifyCrash</u> Violations Disco N N Failure to Maint		
HazMat: No HM transpo	orted	Placard:	Cargo Tank:
C S	Icohol/Controlled Substance Check onducted by Local Jurisdiction ize and Weight Enforcement Screen Inspection	Traffic Enforcement PASA Conducted Inspection Drug Interdiction Search	X Post Crash Inspection PBBT Inspection
State Information: Driver was shown violati	ons: NO		
	rt must be furnished to the motor carrier who d return this report to the address that appea ired certification can result in penalties up to	rs at the top of the left corner of this repo	
return this report with the requ	·		
·	The undersigned certifies that all violations c	on this and any supplemental sheets hav	e been corrected prior to vehicle(s) bein



02788195 UT UT19IN000282

Copy Received By: