



**VEHICLE FACTORS GROUP CHAIRMAN'S FACTUAL REPORT
ATTACHMENT**

NYSDOT CVSA Level V Terminal Inspection March 21, 2018

Schoharie, New York

HWY19MH001

(5 pages)

DRIVER/VEHICLE EXAMINATION REPORT

Query Central 3.4

New York State Department of Transportation
Truck Inspections
50 Wolf Road, POD 5-3
Albany, NY 12232
Phone: (518)457-3406 Fax:

Report Number: NYMC35000868
Inspection Date: 03/21/2018
Start: 12:05 PM ET **End:** 12:36 PM ET
Inspection Level: V - Terminal
HM Inspection Type: None

PRESTIGE LIMOUSINE & CHAUFFEUR SERVICE
 776 SARATOGA RD
 GANSEVOORT, NY 12831-3233
USDOT#: 03180110 **Phone#:** (518)306-7663
MC/MX#: **Fax#:** (518)306-4868
State#:

Driver:
License#: **State:**
Date of Birth:
CoDriver:
License#: **State:**
Date of Birth:

Location: SARATOGA SPRINGS
Highway: 36 WEIBEL AVE
County:

MilePost: **Shipper:**
Origin: SARATOGA SPRINGS, NY **Bill of Lading:** NONE
Destination: SARATOGA SPRINGS **Cargo:** EMPTY

VEHICLE IDENTIFICATION

<u>Unit</u>	<u>Type</u>	<u>Make</u>	<u>Year</u>	<u>State</u>	<u>Plate #</u>	<u>Equipment ID</u>	<u>VIN</u>	<u>GVWR</u>	<u>CVSA #</u>	<u>New CVSA #</u>	<u>OOS#</u>
1	LM	FORD	2001	NY	29056LV		1FMNU40S51EB10299	8,400			

BRAKE ADJUSTMENTS

<u>Axle #</u>	<u>1</u>	<u>2</u>
Right	N/A	N/A
Left	N/A	N/A
Chamber	HYDR	HYDR

VIOLATIONS

<u>Vio Code</u>	<u>Section</u>	<u>Unit</u>	<u>OOS</u>	<u>Citation #</u>	<u>Verify</u>	<u>Crash</u>	<u>Violations Discovered</u>
396.3A1BOS	396.3A1BOS	1	Y		U	N	BRAKES OUT OF SERVICE: The number of defective brakes is equal to or greater than 20 percent of the service brakes on the vehicle or combination: 25% of brakes defective.
390.33-XS	390.33-XS	1	Y		U	N	Operating a Motor Coach or other Passenger Carrying vehicle with seating, secured or unsecured, in excess of the manufacturer's designed seating capacity.: Vehicle missing final manufacturer's tag - vehicle only has MPV FMVSS label (no more than 10 passenger including the driver). Vehicle inspected as 18 seats.
396.3A1B	396.3A1B	1	Y		U	N	Brakes (general) Explain:: Hydraulic brake line going to axle 1 left dangling and is able to make contact with axle 1 left tire.
392.2AU	392.2AU	1	N		N	N	State Operating Authority violation: Vehicle requires NYSDOT Authority to operate for hire. Vehicle is registered in New York as a livery (for hire) vehicle.
392.2RG	392.2RG	1	N		N	N	State vehicle registration or License Plate violation: Vehicle has a seating capacity of greater than 15 including the driver. Livery Plates are not correct for this vehicle.
392.2	392.2	1	N		N	N	Violation of Local Laws - Explain:: Carrier has no USDOT number associated. Go to www.fmcsa.dot.gov/registration .
392.2	392.2	1	N		N	N	Violation of Local Laws - Explain:: Carrier name and USDOT registration number not

Report Prepared By:
CHAD SMITH

Badge #:
M6013

Copy Received By:

Page 1 of 4



03180110 NY NYMC35000868

X _____

X _____

DRIVER/VEHICLE EXAMINATION REPORT

Query Central 3.4

New York State Department of Transportation
Truck Inspections
50 Wolf Road, POD 5-3
Albany, NY 12232
Phone: (518)457-3406 Fax:

Report Number: NYMC35000868
Inspection Date: 03/21/2018
Start: 12:05 PM ET **End:** 12:36 PM ET
Inspection Level: V - Terminal
HM Inspection Type: None

PRESTIGE LIMOUSINE & CHAUFFEUR SERVICE
 776 SARATOGA RD
 GANSEVOORT, NY 12831-3233
USDOT#: 03180110 **Phone#:** (518)306-7663
MC/MX#: **Fax#:** (518)306-4868
State#:

Driver: **State:**
License#:
Date of Birth:
CoDriver:
License#: **State:**
Date of Birth:

<u>Vio Code</u>	<u>Section</u>	<u>Unit</u>	<u>OOS</u>	<u>Citation #</u>	<u>Verify</u>	<u>Crash</u>	<u>Violations Discovered</u>
396.17C	396.17C	1	N		N	N	displayed on both sides of the vehicle in violation of 17 NYCRR 820.1
392.2	392.2	1	N		N	N	Operating a CMV without proof of a periodic inspection: CMV requires proof of periodic inspection.
392.2	392.2	1	N		N	N	Violation of Local Laws - Explain:: Carrier not certified through NYS DMV 19A Bus Driver Unit (VAT 509-A)
396.3A1	396.3A1	1	N		N	N	Inspection, repair and maintenance of parts & accessories: Deterioration of "B" post left side at frame (rusted through)
393.55B	393.55B	1	N		N	N	ABS malfunction indicators for hydr brake sys: ABS Lamp remains on while vehicle is in operation
393.62A	393.62A	1	Y		U	N	No or Defective bus emergency exits: Rear emergency exit window inoperable. Rear compartment right side emergency door inoperable due to child lock being engaged.
393.45DCUV	393.45DCUV	1	N		N	N	Brake Connections with Constrictions Under Vehicle: Axle #2 left side brake has a vice grip attached which constricts hydraulic brake.
392.2	392.2	1	N		N	N	Violation of Local Laws - Explain:: Vehicle missing Final Manufacturer's FMVSS tag. Current tag indicates vehicle as an MPV less than 11 passenger 8400 GVWR.

HazMat: No HM Transported.

Placard: No **Cargo Tank:**

Special Checks:

State Information:

MEC Verified Yes/No: NO; NYS Insp Sticker #: 2707698; Power Unit Mileage: 192600; Through CDLIS Yes/No: NO; Through NYSPIN/NLETS Yes/No: NO;

Report Prepared By:
CHAD SMITH

Badge #:
M6013

Copy Received By:

Page 2 of 4



03180110 NY NYMC35000868

X _____

X _____

DRIVER/VEHICLE EXAMINATION REPORT

Query Central 3.4

New York State Department of Transportation
Truck Inspections
50 Wolf Road, POD 5-3
Albany, NY 12232
Phone: (518)457-3406 Fax:

Report Number: NYMC35000868
Inspection Date: 03/21/2018
Start: 12:05 PM ET End: 12:36 PM ET
Inspection Level: V - Terminal
HM Inspection Type: None

PRESTIGE LIMOUSINE & CHAUFFEUR SERVICE
776 SARATOGA RD
GANSEVOORT, NY 12831-3233
USDOT#: 03180110 Phone#: (518)306-7663
MC/MX#: State#: Fax#: (518)306-4868
State#:

Driver:
License#: State:
Date of Birth:
CoDriver:
License#: State:
Date of Birth:

Vehicle(s) with violations(s), and marked with a "Y" in the OOS column of this report are declared OUT OF SERVICE pursuant to the NYS Transportation Law. No person shall remove the "Out-of-Service Vehicle" sticker or operate such vehicle(s) until the OUT OF SERVICE condition(s) has been repaired. Note: OOS Vehicle violations verified repaired at scene will have an "A" in verify column of the violation

1). DRIVER: Return this TE 241 report to the motor carrier whose name appears at the top.2). REPAIRER: If vehicle defects are listed in the violation section above, please sign the report when repairs are completed.

Signature Of Repairer X: Facility: Date:

3) MOTOR CARRIER: Sign and return within 15 days of issuance, this report ONLY if violations are entered in the violation section. MAILING ADDRESS: New York State Department of Transportation Commercial Motor Vehicle Inspections 50 Wolf Road POD 53 Albany, New York 12232 EMAIL ADDRESS: trucksafety@dot.ny.gov DO NOT SEND TICKETS TO THIS ADDRESS 4) TRAFFIC TICKETS: If issued, MUST be returned to the COURT whose address appears on the front of the TICKET. 5) If you have any reason to question the results of this inspection go to https://dataqs.fmcsa.dot.gov. 6) If the vehicle has NOT been repaired and HAS been permanently removed from service, initial here and sign number 7.7) MOTOR CARRIER CERTIFICATION: I hereby certify that all violations entered on this report have been corrected or have not been corrected in accordance with paragraph 6, and action has been taken to assure compliance with the NYS Transportation Law and Regulations.

Signature Of Motor Carrier X: Title: Date:

Report Prepared By:
CHAD SMITH

Badge #:
M6013

Copy Received By:



03180110 NY NYMC35000868

X

X

DRIVER/VEHICLE EXAMINATION REPORT

Query Central 3.4

New York State Department of Transportation
Truck Inspections
50 Wolf Road, POD 5-3
Albany, NY 12232
Phone: (518)457-3406 Fax:

Report Number: NYMC35000868
Inspection Date: 03/21/2018
Start: 12:05 PM ET End: 12:36 PM ET
Inspection Level: V - Terminal
HM Inspection Type: None

PRESTIGE LIMOUSINE & CHAUFFEUR SERVICE
776 SARATOGA RD
GANSEVOORT, NY 12831-3233
USDOT#: 03180110 Phone#: (518)306-7663
MC/MX#: State# Fax#: (518)306-4868
State#:

Driver:
License#: State:
Date of Birth:
CoDriver:
License#: State:
Date of Birth:

Inspection Notes

Vehicle is missing the Final Manufacturers label. Vehicle only has the incomplete FMVSS manufacturer label that shows the vehicle as an MPV. MPVs are defined in FMVSS as vehicles that are not over 10 passenger including the driver. This vehicle appears to have 18 seats. Inspection conducted at secondary office of the carrier located at roadside inspection address. Lift was not available for inspection. Previously inspected as a 13.080 lbs GVWR 18 seats. Updated on 09-04-18 to reflect USDOT number of entity.

Special Studies No Special Study Data Recorded

Report Prepared By:
CHAD SMITH

Badge #:
M6013

Copy Received By:

Page 4 of 4



03180110 NY NYMC35000868

X _____

X _____