

VEHICLE FACTORS GROUP CHAIRMAN'S FACTUAL REPORT

Vehicle Attachment - 2008 Vanguard Semitrailer Annual Vehicle Inspection Report

Delray Beach, FL

HWY19FH008

(2 pages)

ANNUAL VEHICLE INSPECTION REP **VEHICLE HISTORY RECORD** FLEET UNIT NUMBER 7-30-18 INSPECTOR'S NAME (PRINT OR TYPE) MOTOR CARRIER OPERATOR Compass Lease 8514 No ST. Rd. 33 FORL THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19 ADDRESS YES Lakeland, FL 33809 VEHICLE IDENTIFICATION (AND COMPLETE) LIC. PLATE NO. 20 VIN OTHER CITY, STATE, ZIP CODE INSPECTION AGENCY/LOCATION (OPTIONAL) VEHICLE TYPE ☐ TRACTOR TRAILER ☐ TRUCK ☐ BUS (OTHER) VEHICLE COMPONENTS INSPECTED OK NEEDS REPAIRED DATE OK NEEDS REPAIRED DATE OK NEEDS REPAIRED DATE ITEM ITEM ITEM 1. BRAKE SYSTEM 6. SAFE LOADING 10. TIRES a. Service Brakes a. Part(s) of vehicle or a. Tires on any steering axle b. Parking Brake System condition of loading such of a power unit. that the spare tire or any c. Brake Drums or Rotors b. All other tires. part of the load or dunnage d. Brake Hose c. Installation of speedcan fall onto the roadway. restricted tires unless e. Brake Tubing b. Protection against shifting specifically designated by Low Pressure Warning motor carrier. cargo. 11. WHEELS AND RIMS Tractor Protection Valve c. Container securement a. Lock or Side Ring devices on intermodal h. Air Compressor equipment. b. Wheels and Rims i. Electric Brakes c. Fasteners 7. STEERING MECHANISM j. Hydraulic Brakes d. Welds a. Steering Wheel Free Play k. Vacuum Systems WINDSHIELD GLAZING b. Steering Column I. Antilock Brake System Requirements and exceptions m. Automatic Brake Adjusters c. Front Axle Beam and All COUPLING DEVICES as stated pertaining to any Steering Components crack, discoloration or vision Other Than Steering a. Fifth Wheels reducing matter (reference Column b. Pintle Hooks 393.60 for exceptions). d. Steering Gear Box c. Drawbar/Towbar Eye 13. WINDSHIELD WIPERS d. Drawbar/Towbar Tongue e. Pitman Arm Any power unit that has an e. Safety Devices **Power Steering** inoperative wiper, or missing Saddle-Mounts Ball and Socket Joints or damaged parts that render **EXHAUST SYSTEM** h. Tie Rods and Drag Links it ineffective. a. Exhaust system leaking Nuts 14. MOTORCOACH SEATS forward of or directly below Steering System Any passenger seat that is the driver/sleeper 8. SUSPENSION not securely fastened to the compartment. a. Any U-bolt(s), spring vehicle structure. b. Bus exhaust system hanger(s), or other axle 15. OTHER leaking or discharging in positioning part(s) cracked, violation of standard. List any other condition(s) c. Exhaust system likely to broken, loose or missing which may prevent safe burn, char, or damage the resulting in shifting of an operation of this vehicle. electrical wiring, fuel supply axle from its normal position. or any combustible part of b. Spring Assembly the motor vehicle. c. Torque, Radius or Tracking 4. FUEL SYSTEM Components a. Visible leak. 9. FRAME b. Fuel tank filler cap missing. a. Frame Members c. Fuel tank securely attached. Tire and Wheel Clearance 5. LIGHTING DEVICES c. Adjustable Axle All lighting devices and Assemblies (Sliding reflectors required by Part 393

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.

OK.

Subframes)

NEEDS REPAIR.

IF ITEMS DO NOT APPLY.

shall be operable.

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: