




Vehicle Factors Attachment - 2015 Chevrolet Equinox Tire Scan Summary

Belton, SC

HWY20FH001

(2 pages)



22251856

NTSB Office of Highway Safety
490 L'Enfant Plaza Southwest
Washington, DC 20594-003

Scanned by: NTSB - DP

VIN	- 2GNALBEK5F6	
Vehicle	- Chevrolet, Equinox, LT -	
Tire Size	- P235/55/R18	
License Plate	- SC	Odo: mi.


Vehicle Scan Summary · 12/20/2019, 1:11 PM

Possible Service



Diagnostic Notes




Inspection
Vehicle Color: black



Left Front Tire

Perform Visual Tire Inspection

- Perform Visual Tire Inspection



GOOD

MARGINAL

REPLACE NOW