

Vehicle Factors Attachment – Driver Vehicle Inspection Reports Phoenix, AZ HWY21MH008

(8 pages)

DRIVER'S VEHICLE INSPECTION REPORT AS REQUIRED BY THE D.O.T. FEDERAL MOTOR CARRIER SAFETY REGULATIONS

CARRIER: AZZ	ONA	TICK	TRANSPORT
		TIME:	
TRACTOR/ TRUCK NO.	7	ODOMETER F	READING 4/4293
☐ Air Compressor ☐ Air Lines ☐ Battery ☐ Belts and Hoses ☐ Body ☐ Brake Accessories ☐ Brakes, Parking ☐ Brakes, Service ☐ Clutch ☐ Coupling Devices ☐ Defroster/Heater ☐ Drive Line ☐ Engine ☐ Exhaust ☐ Fifth Wheel ☐ Fluid Levels ☐ Frame and Assembly	Tail/I Turn	anks I/Stop Dash Indicators rance/Marker S S Ssure or	Safety Equipment Fire Extinguisher Flags/Flares/Fusees Reflective Triangles Spare Bulbs and Fuses Spare Seal Beam Starter Steering Suspension System Tire Chains Tires Transmission Trip Recorder Wheels and Rims Windows Windshield Wipers Other
TRAILER(S) NO.(S)	41417		
☐ Brake Connections ☐ Brakes ☐ Coupling Devices ☐ Coupling (King) Pin ☐ Doors	☐ Hitch ☐ Landin ☐ Lights ☐ Reflect ☐ Roof		☐ Suspension System ☐ Tarpaulin ☐ Tires pe ☐ Wheels and Rims ☐ Other
Remarks:			
CONDITION OF THE AB	OVE VEHIC	CLE IS SATISFAC	CTORY
DRIVER'S SIGNATURE: ABOVE DEFECTS CORRECTED ABOVE DEFECTS NEED NOT B		ED FOR SAFE OPERA	TION OF VEHICLE
MECHANIC'S SIGNATURE:			DATE:
ORIGINAL		Copyright 2012 J. J. KELL SA • (800) 327-6868 • Prin	DATE: ER & ASSOCIATES, INC.®, Neenah, WI ted in the United States 185

DRIVER'S VEHICLE INSPECTION REPORT AS REQUIRED BY THE D.O.T. FEDERAL MOTOR CARRIER SAFETY REGULATIONS

CARRIER: ANTONI	Milk Transport	
ADDRESS: Temp	De la	
1/2/61	TIME: 0.700 G	P.M.
DATE: CHECK ANY	TIME: (A.M.). DEFECTIVE ITEM AND GIVE DETAILS UNDER "REMARKS"	P.W.
TRACTOR/ TRUCK NO. 57	ODOMETER READING 4/14	556
☐ Air Compressor ☐ Alr Lines ☐ Battery ☐ Belts and Hoses ☐ Body ☐ Brake Accessories ☐ Brakes, Parking ☐ Brakes, Service ☐ Clutch ☐ Coupling Devices ☐ Defroster/Heater ☐ Drive Line ☐ Engine ☐ Exhaust ☐ Fifth Wheel ☐ Fluid Levels ☐ Frame and Assembly	Front Axle Fuel Tanks Horn Lights Head/Stop Tail/Dash Turn Indicators Clearance/Marker Mirrors Muffler Oil Pressure Radiator Rear End Reflectors Safety Equipment Fire Extinguishe Flags/Flares/Fu Reflective Trian Spare Bulbs an Spare Seal Bea Starter Steering Suspension Syste Tire Chains Trie Chains Tries Transmission Trip Recorder Wheels and Rims Windows Windshield Wiper Other	t sees gles d Fuses m
TRAILER(S) NO.(S)	295	
☐ Brake Connections ☐ Brakes ☐ Coupling Devices ☐ Coupling (King) Pin ☐ Doors	☐ Hitch ☐ Suspension System ☐ Landing Gear ☐ Tarpaulin ☐ Lights - All ☐ Tires ☐ Reflectors/Reflective Tape ☐ Wheels and Rims ☐ Roof ☐ Other	
Remarks:		
•	OVE VEHICLE IS ATISFACTORY	
DRIVER'S SIGNATURE:	1 20 -	
	CORRECTED FOR SAFE OPERATION OF VEHICLE	
MECHANIC'S SIGNATURE:	DATE:	
DRIVER'S SIGNATURE:	DATE:	h, WI
ORIGINAL	USA • (600) 327-6868 • Printed In the United States	1854

DRIVER'S VEHICLE INSPECTION REPORT AS REQUIRED BY THE D.O.T. FEDERAL MOTOR CARRIER SAFETY REGULATIONS

1213		21400-05				
CARRIER: ARIZONA MILLE TRANSPORT						
ADDRESS: TEO PE, AZ						
DATE: 06/03/2	DEFECTIVE ITEM AND GIVE DETAILS UN	DER "REMARKS"				
TRACTOR/ TRUCK NO.	ODOMETER RE	EADING 414821				
Air Compressor Air Lines Battery Beits and Hoses Body Brake Accessories Brakes, Parking Clutch Coupling Devices Defroster/Heater Drive Line Engine Exhaust Fifth Wheel Fluid Levels Frame and Assembly	Front Axle Fuel Tanks Horn Lights Head/Stop Tail/Dash Turn Indicators Clearance/Marker Mirrors Muffler Oll Pressure Radiator Rear End Reflectors	Safety Equipment Fire Extinguisher Flags/Flares/Fusees Reflective Triangles Spare Bulbs and Fuses Spare Seal Beam Starter Steering Suspension System Tire Chains Tries Transmission Trip Recorder Wheels and Rims Windows Windshield Wipers Other				
TRAILER(S) NO.(S)	457					
☐ Brake Connections ☐ Brakes ☐ Coupling Devices ☐ Coupling (King) Pin ☐ Doors	☐ Hitch ☐ Landing Gear ☐ Lights - All ☐ Reflectors/Reflective Tape	☐ Suspension System ☐ Tarpaulin ☐ Tires e ☐ Wheels and Rims ☐ Other				
Remarks:						
CONDITION OF THE ABOVE VEHICLE IS SATISFACTORY						
DRIVER'S SIGNATURE:						
☐ ABOVE DEFECTS CORRECTED						
☐ ABOVE DEFECTS NEED NOT BE	E CORRECTED FOR SAFE OPERATI	ON OF VEHICLE				
MECHANIC'S SIGNATURE:		DATE:				
DRIVER'S SIGNATURE:		DATE: DATE: R & ASSOCIATES, INC.®, Neenah, WI				
ORIGINAL	USA • (800) 327-6868 • Printed	in the United States 1854				

DRIVER'S VEHICLE INSPECTION REPORT

ADDRESS: TIME: A.M. O.L. TRACTOR/ ODOMETER READING 4/4 9 83 TRUCK NO. ☐ Front Axle ☐ Safety Equipment ☐ Air Compressor ☐ Air Lines ☐ Fuel Tanks Fire Extinguisher ☐ Battery ☐ Horn Flags/Flares/Fusees ☐ Belts and Hoses Reflective Triangles □ Lights ☐ Body Spare Bulbs and Fuses Head/Stop ☐ Brake Accessories Tail/Dash Spare Seal Beam Brakes, Parking Turn Indicators Starter ☐ Brakes, Service Clearance/Marker Steering ☐ Clutch ☐ Mirrors Suspension System □ Coupling Devices ☐ Muffler Tire Chains Defroster/Heater Oil Pressure ☐ Tires ☐ Drive Line ☐ Radiator ☐ Transmission Engine Trip Recorder ☐ Rear End ☐ Exhaust ☐ Reflectors Wheels and Rims ☐ Windows Fifth Wheel ☐ Fluid Levels Windshield Wipers Other Frame and Assembly 45 TRAILER(S) NO.(S) ☐ Brake Connections ☐ Hitch Suspension System ☐ Brakes ☐ Landing Gear □ Tarpaulin ☐ Lights - All ☐ Tires☐ Reflectors/Reflective Tape☐ Wheels and Rims ☐ Coupling Devices ☐ Coupling (King) Pin Roof ☐ Doors Other Remarks: ☑ CONDITION OF THE ABOVE VEHICLE IS SATISFACTORY DRIVER'S SIGNATURE: □ ABOVE DEFECTS CORRECTED ABOVE DEFECTS NEED NOT BE CORRECTED FOR SAFE OPERATION OF VEHICLE MECHANIC'S SIGNATURE: DATE:

USA • (800) 327-6868 • Printed in the United States

1854

DRIVER'S SIGNATURE: .

ORIGINAL

DRIVER'S VEHICLE INSPECTION REPORT

ARIZONA MICK TRANSPORT ADDRESS: CK ANY DEFECTIVE ITEM AND GIVE DETAILS UNDER HEMARKS TRACTOR/ ODOMETER READING 4/5/83 TRUCK NO. ☐ Safety Equipment ☐ Front Axle ☐ Air Compressor Fire Extinguisher Fuel Tanks ☐ Air Lines Flags/Flares/Fusees □ Battery ☐ Horn Reflective Triangles ☐ Lights ☐ Belts and Hoses Spare Bulbs and Fuses Head/Stop ☐ Body Spare Seal Beam Tail/Dash ☐ Brake Accessories ☐ Starter Turn Indicators ☐ Brakes, Parking Steering Brakes, Service Clearance/Marker ☐ Suspension System ☐ Clutch Mirrors ☐ Tire Chains ☐ Muffler □ Coupling Devices Oil Pressure Tires Defroster/Heater ☐ Transmission □ Radiator ☐ Drive Line Trip Recorder Rear End □ Engine □ Reflectors Wheels and Rims Exhaust Windows Fifth Wheel Windshield Wipers ☐ Fluid Levels Other ☐ Frame and Assembly TRAILER(S) NO.(S) Suspension System ☐ Hitch ☐ Brake Connections Landing Gear ☐ Tarpaulin □ Brakes ☐ Lights - All ☐ Tires ☐ Reflectors/Reflective Tape ☐ Wheels and Rims ☐ Coupling Devices Coupling (King) Pin Other Roof □ Doors Remarks: CONDITION OF THE ABOVE VEHICLE IS SATISFACTORY DRIVER'S SIGNATURE: □ ABOVE DEFECTS CORRECTED ☐ ABOVE DEFECTS NEED NOT BE CORRECTED FOR SAFE OPERATION OF VEHICLE MECHANIC'S SIGNATURE: DRIVER'S SIGNATURE: 1854 **ORIGINAL**

DRIVER'S VEHICLE INSPECTION REPORT

ARIZONA TIKK TRANSPORT ADDRESS: TRACTOR/ ODOMETER READING 4/5458 TRUCK NO. ☐ Safety Equipment ☐ Front Axle Air Compressor Fire Extinguisher Air Lines ☐ Fuel Tanks Flags/Flares/Fusees □ Battery ☐ Horn Reflective Triangles ☐ Lights Belts and Hoses Spare Bulbs and Fuses Head/Stop □ Body Spare Seal Beam Tail/Dash □ Brake Accessories ☐ Starter Turn Indicators Brakes, Parking ☐ Brakes, Service Clearance/Marker Steering Suspension System ☐ Clutch ☐ Mirrors Tire Chains Muffler □ Coupling Devices ☐ Defroster/Heater Oil Pressure Tires Transmission □ Radiator ☐ Drive Line □ Trip Recorder 🗌 Rear End ☐ Engine Reflectors ☐ Wheels and Rims ☐ Exhaust ☐ Windows ☐ Fifth Wheel ☐ Windshield Wipers Fluid Levels □ Other ☐ Frame and Assembly 471 TRAILER(S) NO.(S) Suspension System
Tarpaulin
Tires ☐ Hitch ☐ Brake Connections ☐ Landing Gear
☐ Lights - All
☐ Reflectors/Reflective Tape
☐ Other
☐ Hitch
☐ Landing Gear
☐ Tires
☐ Wheels and Rims
☐ Other ☐ Brakes ☐ Coupling Devices ☐ Coupling (King) Pin Doors Remarks: CONDITION OF THE ABOVE VEHICLE IS SATISFACTORY DRIVER'S SIGNATURE: ☐ ABOVE DEFECTS CORRECTED ☐ ABOVE DEFECTS NEED NOT BE CORRECTED FOR SAFE OPERATION OF VEHICLE MECHANIC'S SIGNATURE: . DRIVER'S SIGNATURE: © Copyright 2012 J. J. KELLER & ASSOCIATES, INC.®, Neenah, WI

USA • (800) 327-6868 • Printed in the United States

ORIGINAL

1854

DRIVER'S VEHICLE INSPECTION REPORT AS REQUIRED BY THE D.O.T. FEDERAL MOTOR CARRIER SAFETY REGULATIONS

1717	2-111 87					
CARRIER: ARIZONA MICK TRANSPORT						
ADDRESS: 72970-E, 12						
DATE: OC/OS/202/ TIME: A.M. 02:00 P.M.						
TRACTOR/ TRUCK NO. 57 ODOMETER READING 4/57/7						
Air Compressor Air Lines Battery Belts and Hoses Body Brake Accessories Brakes, Parking Brakes, Service Clutch Coupling Devices Defroster/Heater Drive Line Engine Exhaust Fifth Wheel Fluid Levels Frame and Assembly	Front Axle Fuel Tanks Horn Lights Head/Stop Tail/Dash Turn Indicators Clearance/Marker Mirrors Muffler Oil Pressure Radiator Rear End Reflectors	Safety Equipment Fire Extinguisher Flags/Flares/Fusees Reflective Triangles Spare Bulbs and Fuses Spare Seal Beam Starter Steering Suspension System Tire Chains Tries Transmission Trip Recorder Wheels and Rims Windows Windshield Wipers Other				
TRAILER(S) NO.(S)	438					
☐ Brake Connections ☐ Brakes ☐ Coupling Devices ☐ Coupling (King) Pin ☐ Doors	☐ Hitch ☐ Landing Gear ☐ Lights - All ☐ Reflectors/Reflective Tape ☐ Roof	Suspension System Tarpaulin Tires Wheels and Rims Other				
Remarks:						
	100					
		- A				
CONDITION OF THE ABOVE VEHICLE IS SATISFACTORY						
DRIVER'S SIGNATURE:						
☐ ABOVE DEFECTS CORRECTED						
ABOVE DEFECTS NEED NOT BE CORRECTED FOR SAFE OPERATION OF VEHICLE MECHANIC'S SIGNATURE:						
MECHANIC'S SIGNATURE: DRIVER'S SIGNATURE:		DATE:				
ORIGINAL © Copyright 2012 J. J. KELLER & ASSOCIATES, INC.®, Neenah, WI USA • (800) 327-8868 • Printed in the United States 185						