


## **Violations within ¼ mile of 1644 & 1646 Park Avenue, Manhattan**



The green circle represents the ¼ mile radius around the incident location.

MB00000585 – 1395 5<sup>th</sup> Ave, Manhattan

### **From 2011 Record Audit**

#### **255.748(b) - Valve maintenance: Service line valves**

The following service line valve inspections, associated with buildings of public assembly, exceeded the 15 month inspection timeframe.

Valve Number	Initial Inspection	Subsequent Inspection	Finding
MB00000585	5/10/09	8/24/10	Exceeded 15 months