



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety

Western Pacific Region

July 13, 2017

ACCIDENT REPORT PHOTOGRAPHS

WPR20CA080

This document contains 03 embedded photos.

(3 pages)



Photo 1: View of wrinkled Rudder (GYR Airport Ops)



Photo 2: Tailwheel chains and hardware (GYR Airport Ops)



Photo 3: Underneath view of tail section (GYR Airport Ops)