



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety

Western Pacific Region

May 24, 2020

ACCIDENT REPORT PHOTOGRAPHS

WPR20CA132

This document contains 01 embedded photos.

(2 pages)



Photo 1: Underside view of airplane. Note damage to the right wing (Airport Ops)