



**Photo 1 – View of right stabilizer damage (photo courtesy of Owner)**



**Photo 2 - View of left speed brake damage (photo courtesy of Owner)**