



Photo 1 – View of accident site wreckage. (Photo Courtesy of FAA)



Photo 2 – View of left engine.



Photo 3 – View of left engine with hole in upper case.