



**Photo 1 – Wreckage from front (NTSB)**





**Photo 2 – Wreckage from right side (NTSB)**





**Photo 3 – Wreckage from left side (NTSB)**





**Photo 4 – View of impacted trees (NTSB)**





**Photo 5 – Engine with cowling partially removed (FAA)**