## $WPR22LA324\ Accident\ Pictures-courtesy\ of\ FAA$



Figure 1: View of right pedal disconnected from the brake cylinder.



Figure 2: View of the clevis pin.