

WPR23LA112

**INVESTIGATION PHOTOGRAPHS**



**Photograph 1 - View of Accident Site (Courtesy of FAA)**



**Photograph 2 - Right Side View of Main Wreckage (Courtesy of FAA)**



**Photograph 3 - Rear View of Main Wreckage (Courtesy of FAA)**



**Photograph 4 - Left Side View of Main Wreckage (Courtesy of FAA)**



**Photograph 5 - View of Debris (Courtesy of FAA)**



**Photograph 6 - View of Wing (Courtesy of FAA)**



**Photograph 7 - Airplane Debris in Tree (Courtesy of FAA)**





**Photograph 8 - View of Engine (Courtesy of FAA)**



**Photograph 9 - Top View of Engine (Courtesy of FAA)**