

WPR23LA236 Accident Pictures (Courtesy of Insurance Representative).



Figure 1: Airplane as viewed from the right side.



Figure 2: Left wing as viewed from the top.



Figure 3: Left wing as viewed from the top.



Figure 4: Right wing as viewed from the top.