



1. Main wreckage
2. Fuel tank
3. Main rotor blade fragment
4. The Racquet Club contained a large debris area of airframe and cockpit fragments



1. Main rotor blade fragment

- | | | | |
|---------------------------------|--|--|--------------------------------------|
| 1. Plexi-glass | 6. Tinted Plexi-glass | 11. Multiple Plexi-glass fragments (>20) | 16. Top of Fire Extinguisher |
| 2. Fiberglass | 7. Fiberglass | 12. Blade Fragment | 17. Black metal fragment |
| 3. Plexi-glass | 8. Battery Cover, multiple pieces of Plexi-glass, Fiberglass | 13. Metal Fragment | 18. Red painted metal |
| 4. Tinted Plexi-glass | 9. Tinted Plexi-glass, multiple pieces (7), Skid tip | 14. Ear Cup | 19. Red painted metal (part of door) |
| 5. Safety for Fire Extinguisher | 10. Not related to accident | 15. Headphone Chord | 20. Main Rotor blade fragment |



- | | | | |
|---|----------------------------------|----------------------------------|---------------------------------|
| 21. Door | 26. Instrument housing fragment | 27.5 Instrument housing fragment | 30. Plexi-glass fragments (>15) |
| 22. Sunglasses (frame and two liberated lenses) | 27.1 Sheet metal | 27.6 Pen | 31. Cell Phone |
| 23. Rubber piece | 27.2 instrument housing fragment | 27.7 Instrument housing fragment | |
| 24. Camera mount or latch | 27.3 Red sheet Metal | 27.8 Altimeter pieces | |
| 25. Shoe Sole | 27.4 Door Hinge | 29. Fire Extinguisher | |



N808NV

Ful Tank

Headset Speaker

Right Shoe

Left Shoe, Wire Clamp, Mixture Control Guard

Altimeter Face Plate

Plexi-Glass frag

Camera Case

Racquet Club

Carpet and Plexi-glass

Blade Fragment

