

PHOTOGRAPHS



Figure 1: Damage to the Wing



Figure 2: Airplane after the Accident




Figure 3: Damage to the Wing Spar





Figure 4 and 5: Representation Showing the Turn from the Runway to Taxiway ZZ




Figure 6 and 7: Representation Showing the Turn and Initial Encounter of the Wind Produced by the Turbo-Prop Airplane's Propellers



Figure 7 and 8: Representation Showing the Accident Airplane Being Blown Sideways




Figure 9 and 10: Representation Showing the Location the Airplane's Left Wing Contacted the Runway and after it was Spun



Figure 11: Where the Airplane Came to Rest