

Track Outage Management

Incident Detail

Incident Num	Description	CRTN USER ID	Reporting Train	Duration (mins)
9198518	Wash Out on MIDLOTHIA	N SUB 04/18/2019 03:15 CDT	1	255
category	Weather		Type Wash Out	
Region	Southern	Serv Unit TEXOMA	Subdiv MIDLOTHIAN SUB	Milepost 49.00
Circ 7	BV270	Station MARA, TX		
Start	4/18/2019 3:15:00 AM	Notifd	On Scene	End 4/18/2019 7:30:00 AM
Created	4/18/2019 3:20:36 AM	Created by	Sys Ref ID	Incident

Notes				
0323- 1 r	otified			
0425-			, ETA 050	00
0 0315- notified a	reported ballast washind en route ETA 0400.			Midlothian Sub,
0555: ALL CLEAR	ON MIDLOTHIAN WASI	HOUT. NOTHIN	IG AFFECTED	
Train	Delay Mins	Delay Hrs	Recrew	
Total train dela	ay hours			
Avg train dela	ny hours			