

**On Scene Photos**  
Courtesy of the Federal Aviation Administration



*Figure 1: Overview of the Left Wing*



*Figure 2: Close View of Left Wing Damage*

**On Scene Photos**  
Courtesy of the Federal Aviation Administration



*Figure 3: The PAPI Mount*



*Figure 4: The PAPI Itself*