

On Scene Photos
Courtesy of Airport Operations



Figure 1: Overall View of Airplane



Figure 2: Rudder Damage

On Scene Photos
Courtesy of Airport Operations



Figure 3: Upper Left Wingtip Damage

END.

Submitted by: Samantha Link